ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0257, W0112, W0275, W0196, W0198, W0253	NA	Kamath Layout
Segment No.	**Total Length (m)**	
10/C-W0257/S114615	130.21	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	24.87	77.558821	13.063085	77.558790	13.062863	W0196	W0198
2	18.94	77.557944	13.063750	77.557968	13.063581	W0112	UP DRAIN LINE
3	86.40	77.557138	13.063704	77.557934	13.063750	W0257	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of RCC Drain at Kamath Layout in ward no 10 (Doddabommasandra) Vidyaranayapura Sub-Division Yelahanka zone	1000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	RCC Drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of RCC Drain at Kamath Layout in ward no 10 (Doddabommasandra) Vidyaranayapura Sub-Division Yelahanka zone	010-16-000020
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/247/2015-16	26/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
26/02/2016	25/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
MADAN KUMAR.H.V		0.00
Phone No.	**E-Mail ID**	

9886162619

Field Inspection Details

Number of Trees	Any Other Information	Name
2		MADHAVA RAO
Date of Inspection	**Remarks**	
27/06/2016	completed	

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0257, W0112, W0275, W0196,

Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/06/2016	27/07/2016	COMPLETED
SE	VASU K M	27/06/2016	27/07/2016	COMPLETED
EE	YARAPPA REDDY	27/06/2016	27/07/2016	COMPLETED
AEE	SHIVAKUMAR	27/06/2016	27/07/2016	COMPLETED
AE	MADHAVA RAO	27/06/2016	27/07/2016	COMPLETED
AE	MADHAVA RAO	27/06/2016	27/07/2016	COMPLETED

Jeetha
AE W-10

27/6/16

ASSISTANT EXECUTIVE ENGINEER
Vidyaranyapura Sub-Division
Bruhath Bengaluru Mahanagara Palike

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0257, W0112, W0275, W0196,